Approved For Reli	NION GEODET lease 2003/08/12 : CIA-RDP8	5X1 82-00457R0156		25X
TOPI Brandeniv researedo A	irfield		16. 1	
10110 amazana manaki dadikhi dadiki indigari da bila dadaka mana	P Jacquist - Marting Balling Statement of the control of the c	department of the comment of the com	Spiriture Endra Print District Annual Control of the Control of th	nedistrian view. A. versität nei een saltsaapsesti vied
EVALUATION	PLACE OBTAINED		The second secon	25X1
DATE OF CONTENT 17 to 1 November	bor 1952	SAMENHER TO AGE OF STREET OF STREET CHARGE AND AN AND AN AND AN AN	a Trougas cappios acabates not apertural states Agrees at 1 Februarity (4)	Nagaragas composition and an american and an appropriate contracts
	, '	RED 25 Novo	mbor 1952	
DATE OBTAINED	25X1	l V (as LV vacana aligno en equinament		er mennen unter di militaria della sensa e una distanti una di sensa e una distanti una di sensa e una distanti
REFERENCES	Balt spiriture multiment the vote and control and an	Carriera da Carro de	Mart An University respect to a direct to the Street	Parisher with at emperorate technique acceptable at
PAGES 2 ENCLOSURES	(NO. & TYPE)	description and in communicative day in A. p. C. deciminated days	Militarovan Militarova Militarova regulación e del los 2020es in hoto, e valuable en de l	Standarder verland unterstätter Kill (Madhaiz)
REMARKS		MINISTER OF STREET, ST	all the new wife specimen and specimen as the second specimen as the second specimen as the second specimen as	er minner men men sen sen sen sen sen sen sen sen sen s
DEC		1		
			titigeneider verder vierbreitliche utlikertenden die zur Angleichen glass (antenderfüllig)	
DO NOT CIRCL	ULATE	A STATE OF THE STA	-Chivarre Explanation to the graph of the chival Explanation of the As Affiliates in the	necessarium and antique and antique and a second a second and a second a second and
2	25X1		ingegreen en	Sandarian State and Assessment State .
		-		
	raft and air activity we			25
2 and 3 p.m., 32 IL exercise. 1 18 October. At noo 21 October. Landin engine transport at 23 October. At 3 p 27 October. Thirty was no flying throu 28 October. A Po-2 served up to 3 p.m. 29 October. There or 4 km, and the cl p.m. and 3:10 p.m., field were continuo vity were parked on	2 biplane took off at 1:	rved outside 10 each at 128 IL-10s were the 130 p.m. No many ity. The visitude of about the 130 p.m. Ity is and low-14 is an	the hangars. 10 and 11 a,n, and re counted at the Landing field. If ield at 3:10 p.: 10 and 11 a,n, and recounted at the landing field. 11 and 12	om and twin field. There was obted to 3 oween 1:15 the landing
1	. Subsequently, the	rlanes taxis	ed to the dispersa	ıl area
of the hangars. An of the hangars, hav 31 October to 4 Nov	n corner of the field. I additional about 15 IL- ve not yet returned to the vember. Thirty to 32 II y between 31 October and	thirty-one II -10s, which we ne field. 10s were pa	-los were counted were usually parked arked at the field	l in front ed in front
2. 18 November. There 19 October. No air	was no air activity. To activity.			
dull weather. No mo 21 October. After	n 9:30 and 9:52 a.m., or ore flights were made. 8 a.m., there was littl			
23 October. Twenty- propeller hubs and	visibility was poor. -three IL-10s were parko red upper edges on the arked farthest north at	rudder assen	mblies were obser	red on
				ide -
				ide -

24 October, No air activity although the weather was good. The green radio truck with a rod antenna and a box of mesh wire on its roof was observed leaving the barracks installation and proceeding toward the landing field. 25 October. Maintenance work was in progress on individual IL-10s but no flights were performed. 26 October. The number of aircraft was unchanged. There was no air activity.
31 October to 3 November. There was no air activity. The weather usually was bad.
4 November. About 25 II-10s were parked in front of the hangars. At 10 a.m., an 25X1 IL-10 plane without a weapon in the rear section of the cabin took off. upper edge of the rudder assembly and the propeller hub. Subsequently, individual lasting 45 to 60 minutes were made by the plane. 3. Seventeen shraphelproof aircraft revetments, including 10 in the northeastern corner and 7 in the northwestern corner, were completed. An additional 7 revetments were under construction in the southeastern corner of the field. Forty to 60 soldiers wearing red-bordered black epaulets were usually working on the site.3 25X1 5. On 28 October, there was no air activity at the field. Night IL-10s. were parked in the northern corner of the field. An addi-25X1 tional 30 to 35 IL-10s, all of which had red propeller hubs, were observed in front of the hangars on the eastern edge of the field. Shrapnelproof aircraft revetments were under construction on the northern edge of the field. Thirteen such revetments were counted. 25X1

SECRET/